

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-029071**Date Inspected:** 25-Jan-2013**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1730**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** S.A.S. Job site**CWI Name:** N / A**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** S.A.S. Structure**Summary of Items Observed:**

The Caltrans Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI accompanied the Caltrans Transportation Engineers Thuc Tran and Thanh Le, and conducted a survey of the exterior of the Orthotropic Box Girders (OBG) of the SAS structure. The survey was conducted from all accessible locations on the temporary trestle. The QAI assisted in documenting work that is not completed at this time and areas where the paint has visible damage. The QAI noted that the contractor has begun to remove the temporary trestle and additional surveys / work will be difficult to accomplish. The QAI provided the survey information to the Assistant Structural Materials Representative (ASMR) Laura Webb.

The QAI reviewed contract documents at pier 7. The QAI used approved weekly welding report submittals and cross referenced the welding and inspection status as reported with QA records to identify the overall weld status. The QAI continued reviewing the contractor's submitted Electro-Slag Welding (ESW) reports and referencing the Requests for Weld Repair (RWRs) in order to determine the status of completion of the repairs and welds' overall reported condition. The QAI continued reviewing welding report submittals 1536R142 & R143 for contract conformance. This work was in progress at the end of the shift.

Summary of Conversations:

The QAI relayed the status of the document / submittal reviews to the QAI Lead Danny Reyes. Except as described above, there were no other notable conversations.

Comments

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas, (916) 764-6027, who represents the Office of Structural Materials for your project.

Inspected By:	Croff, Scott	Quality Assurance Inspector
Reviewed By:	Reyes, Danny	QA Reviewer
